

Volkswagen Collision Repair Standards

Supplemental Restraint System Wiring Harnesses

Applicable to All Volkswagen Models

Volkswagen designs and equips their vehicles with the latest crashworthy features to help ensure optimum occupant safety. In maintaining these standards, Volkswagen is providing collision repair centers with critical information pertaining to collision repair/parts replacement on Volkswagen vehicles.

Damaged Supplemental Restraint System (SRS) wiring or wiring connectors require replacement of the wiring harness. It is necessary to follow all precautions and replacement procedures found in the Volkswagen model-specific repair manual for SRS wiring and wiring components.

Any SRS wiring, wiring connectors, or wiring harnesses near the area of collision damage should be thoroughly examined.

Volkswagen approves only repairs made with Genuine Volkswagen Parts. Aftermarket, salvage, or remanufactured SRS airbag system parts do not meet the exacting specifications of Genuine Volkswagen Parts and therefore are not an acceptable method of repair on any Volkswagen vehicle. These parts may depreciate the value of the vehicle and/or put the vehicle occupants at risk. Aftermarket, salvage, and remanufactured parts or failure of another Volkswagen part caused by the installation or improper performance of an aftermarket, salvage, or remanufactured part is not covered under Volkswagen's new vehicle limited warranty.

NOTE: Do NOT attempt to repair the SRS wiring system or related components on any Volkswagen vehicle. Replace any damaged or bent SRS components with Genuine Volkswagen Parts. Some fasteners and clips are non-reusable; refer to the Volkswagen repair manual for more information.

PLEASE DISTRIBUTE THIS DOCUMENT TO THE FOLLOWING: COLLISION REPAIR CENTER MANAGERS, ESTIMATORS, AND TECHNICIANS.